



Photo #1
Durar Avenue looking west to
east



Photo #2
Durar Avenue low point. The
B Inlets are atop the 48" RCP
connecting the Middle and
Lower Detention ponds



Photo #3
View looking west across
Middle Detention pond at rear of
Kira Lane Townhouse Units
perched atop the landscape
tie retaining walls



Photo #4
View looking south down
Middle Detention Pond from
atop pool retaining wall



Photo #5
View looking north along
tiered landscape tie retaining
wall behind Kira Lane
Units 35-41



Photo #6
View of tiered landscape tie
retaining wall to the rear of
Kira Lane Units 35-41



Photo #7
Front view of Kira Lane
landscape tie wall above
Middle Detention pond



Photo #8
Kira Lane tiered landscape
wall looking north



Photo #9
Kira Lane landscape tie wall
looking south



Photo #10
24" Maple growing atop
landscape tie wall between
Units 41 & 43



Photo #11
Inside corner of landscape tie retaining wall. The ACP sewer line is between the wall and townhomes




Photo #12
Outside corner at the
"Narrows" Sanitary Sewer
manhole to rear of wall




Photo #13
View of the narrows between
the Upper and Middle
Detention Ponds



Photo #14
View of the tiered landscape tie
wall behind Kira Lane
Units 43-49 above the Upper
Detention Pond.
Looking north ACP sewer line is
between wall and townhomes



Photo #15
View of the tiered landscape tie
wall behind Kira Lane
Units 43-49 above the Upper
Detention Pond.
Looking north ACP sewer line is
between wall and townhomes



Photo #16

**View of the tiered landscape tie
wall behind Kira Lane
Units 43-49 above the Upper
Detention Pond.**

**Looking north ACP sewer line is
between wall and townhomes**

Photo #17

**View of Kira Lane tiered
landscape tie wall above Upper
Detention Pond looking south**





Photo #18
View looking through the
narrows north to south at the
Middle Detention Pond. Choked
and silted CMP culvert in
foreground



Photo #19
View looking east across Upper
Detention Pond at the 32"x54"
CMP storm sewer headwall and
the bamboo grove



Photo #20
90° corner of the tiered
landscape tie retaining wall
supporting the pool



Photo #21
West face of pool tiered
landscape wall above Middle
Detention Pond



Photo #22
Saw tooth landscape tie wall to
rear of Units 19-25 above
Lower Detention Pond



Photo #23
Saw tooth wall above Lower
Detention Pond. Note steep
slope and absence of woody
vegetation



Photo #24
North end of saw tooth wall to
rear of Unit 25 with Lower
Detention Pond in background



Photo #25
Sanitary sewer manhole at
south end of wall



Photo #26
Inlet end of outlet control
structure at south end of Lower
Detention Pond



Photo #27
Outlet end of outlet control
structure



Photo #28
Outlet end of outlet control
structure