



Photo #40
Cedar Avenue curb cut leading
to Emergency Access, silt
chamber sanitary sewer and
drainage easement.



Photo #41
Cedar Avenue curb cut leading
to Emergency Access, silt
chamber sanitary sewer and
drainage easement.



Photo #42
Traveled way of Cedar Avenue.
Emergency Access driveway.



Photo #43
Cedar Avenue Emergency
Access driveway. Shows sewer
manhole, silt chamber, gate and
fence lines.



Photo #44
Cedar Avenue Emergency
Access driveway showing
sanitary manhole, silt
chamber, fence lines.
Inside the Hopper Ridge
property line.



Photo #45
Gate on the Emergency
Access driveway in line with
north end of the north upper
detention pond.



Photo #46
Emergency Access driveway
at rear corner of Lot 1, #388
Cedar Avenue. Note the
concrete pavers.



Photo #47
View of Emergency Access
driveway looking north
towards Cedar Avenue.



NO
TRESPASSING
VIOLATORS
WILL BE
PROSECUTED

Photo #48
Emergency Access driveway
approaching the proposed
stockpile area.



Photo #49
View of proposed stockpile
area looking north to south.



Photo #50
Stockpile area looking east to
west.



Photo #51
Tibor Latincsics at base of
walls on west side of the upper
north detention pond in
approximate location of
#43 Kira Lane